INDEX

(The first number cited is the issue number)

Author Index

Allen, Taylan ... 3—44-45
Bergmann, H. Robert ... 2—17-19
Boggerdus, K. O. ... 1—22-30
Bolt, S. H. ... 1—63-64
Cady, J. L. ... 3—46-47
Crane, J. ... 1—63-64
Crawford, R. R. ... 3—36-43
Croucher, Thomas R. ... 2—6-11
Dawson, R. N. ... 1—33-39
Dewez, F. J., Jr. ... 4—50-55
Doelker, W. J. ... 2—32-34
Donachie, M. J., Jr. ... 4—1-11
Dresher, W. H. ... 3—32-35
Eberly, Warren S. ... 1—40-47
Eisenstein, H. L. ... 4—20-25
Espich, R. E. ... 1—33-39
Feerster, G. S. ... 3—25-30
Friedman, Gerald ... 1—48-50
Gerds, Arnold ... 3—44-45
Gentzel, C. G. ... 2—53-61
Gouda, R. J. ... 4—39-49
Gentzel, Francois B. ... 2—35-47
Green, Allen T. ... 1—61-62
Gunnarson, S. ... 1—5-9
Henson, Darrell C. ... 3—22-23
Holt, Marshall ... 1—22-30
Hughes, Robert L. ... 2—1-3
Hurley, J. L. ... 3—36-43
Judy, R. W., Jr. ... 4—39-49
Kaltenhauser, R. H. ... 2—41-47
Kelley, E. W. ... 1—10-16
Kern, Roy F. ... 1—1-4
Kitchin, A. L. ... 3—36-43
Korbonski, J. A. ... 3—47-48
Kosinski, Edward ... 1—48-50
Krauss, G. ... 4—25-30
Lange, E. A. ... 4—31-39
Latchaw, R. F. ... 2—24-26
Lauchner, E. A. ... 2—47-52
Lawrence, G. D. ... 3—25-30
Lee, Edward W. ... 2—4-5
Malcolm, R. C. ... 1—22-30
Manjoine, M. J. ... 1—31-33
Melville, A. G. ... 4—50-55
Mitchell, J. R. ... 4—50-55
Moore, Terry L. ... 1—16-22
Murr, L. E. ... 3—47-48
Muzyka, Donald R. ... 4—12-20
Osborn, H. B., Jr. ... 3—13-15
Otto, Henry E. ... 1—62-63
Pehlke, R. D. ... 3—9-13
Plant, Harold C. ... 3—4-7
Pike, J. N. ... 3—32-35
Rubin, Norbert C. ... 3—30-32
Ryan, Joseph ... 4—56-59
Schuerger, Thomas R. ... 3—1-4
Shannon, John D. ... 3—8-9
Shoemaker, R. H. ... 2—38-41
Smith, G. V. ... 4—59-61
Soviak, Michael ... 3—16-17
Spillane, D. J. ... 2—24-26
Sullivan, C. P. ... 4—1-11
Taylor, Edward ... 2—12-16
Tiskus, John R. ... 3—1-4
Tressler, Richard E. ... 1—16-22
VanDerHeyden, R. L. ... 2—27-31
Webbere, F. J. ... 1—33-39
Weisinger, M. D. ... 3—17-25
Whitney, C. R. ... 4—25-30
Williams, R. R. ... 2—20-21
Wood, W.G. ... 2—38-41
Zukas, Eugene G. ... 1—51-60

Subject Index

Abrasive cutoffs
  of Al-B composites ... 3—18-19
Agitation
  in quenching ... 2—17-19
Aircraft industry
  alkaline cleaning ... 3—47
  emulsion cleaning ... 3—46
Alkaline cleaning
  in aircraft industry ... 3—47
Aluminum
  addition to Fe superalloys ... 4—25-30
  use of synthetic quenchants ... 2—7-9
Aluminum alloy forgings
  design ... 2—48-49
  fitup ... 2—51
  machining ... 2—50
  material ... 2—49
  process ... 2—49-51
  protective coatings ... 2—51
  shot peening ... 2—51
  straightening ... 2—50
  stress-corrosion cracking ... 2—47-52
Aluminum alloys
  DT test ... 4—41-45
  development for bearings ... 1—34-39
  fracture extension resistance ... 4—39-49
  fracture resistance ... 4—37-38
  R-curve ... 4—42, 45-48
Aluminum alloys, specific types
  Al-babbit
    in development of bearings ... 1—36-37
    metallography ... 1—36-37
  Al-Cu powder
    atomizing ... 3—27
    mold materials ... 3—28
    oxide film ... 3—28-29
    pressureless sintering ... 3—26-30
    storing ... 3—27-28
  Al-Mg powder
    atomizing ... 3—27
    mold materials ... 3—28
    oxide film ... 3—28-29
    pressureless sintering ... 3—26-30
    storing ... 3—27-28
  Al-Si powder
    atomizing ... 3—27
    mold materials ... 3—28
    oxide film ... 3—28-29
    pressureless sintering ... 3—26-30
    storing ... 3—27-28
  2014
    shock hardening ... 1—62-63
  2024
    shock hardening ... 1—62-63
  2219
    shock hardening ... 1—62-63
  7039
    shock hardening ... 1—62-63
  3003-0
    creep strength ... 1—26-28
    mechanical properties ... 1—24-30
    rupture strength ... 1—26
    tensile strength ... 1—25-26
    yield strength ... 1—26
Aluminum-boron composites
  abrasive cutoff ... 3—18-19
  brake bending ... 3—22-24
  drilling ... 3—19-20
  forming ... 3—21-25
  grinding ... 3—18
  machining ... 3—18-21
  milling ... 3—18
  stretch forming ... 3—21-22
  testing ... 3—18
Annealing
  in vacuum furnaces ... 2—27-28; 2—33
  of Ni superalloys ... 1—12
  use of salt baths ... 3—16
Atmosphere
  control by infrared CO_2 ... 2—1-3
Atomizing
  of Al powder ... 3—27
Austempering
  use of salt baths ... 3—16
Automatic control
  in carburizing furnaces ... 1—5-9
Automobile parts, Renault
  case hardening and carbonitriding ... 2—36-37
  forging ... 2—35
  heat treatment ... 2—35-37
  induction ... 2—36
Axle shafts
  use of induction hardening ... 3—13
Bend ductility
  of Ni superalloys ... 1—15
Bearing race cups
  use of induction hardening ... 3—15
Bearing rib rings
  use of induction hardening ... 3—15
Bearings
  Al-Pb system ... 1—34-31
  continuous casting ... 1—35-36
  development of M-390 bearing ... 1—35-39
  properties ... 1—34
Bearings, specific types
  M-390
    development ... 1—35-39
Blades
  vacuum heat treating ... 2—25
Boron
  in Fe superalloys ... 4—7

Brake bending
of Al-B composites ... 3–22-24
Business machines
use of vacuum furnaces in manufacture ... 2–27-31; 2–32-34
Carbides
in Fe superalloys ... 4–5-7
Carbon dioxide
use in atmosphere control ... 2–1-3
Carbonitriding
of automobile parts ... 2–36
Carburizing
use of salt baths ... 3–16
Carburizing furnaces
automatic control ... 1–5-9
C penetration curves ... 1–7-9
production furnaces ... 1–5-7
Case hardening
of automobile parts ... 2–36-37
Cast blades
vacuum heat treating ... 2–24
Cast vanes
vacuum heat treating ... 2–25
Casting
of Fe superalloys ... 4–8
of Ni superalloys ... 1–10-11, 13
Closed-die forging
effect of temperature ... 3–44-45
Coatings
of Al alloy forgings ... 2–51
Cobalt alloys, specific types
MP35N
properties ... 2–62-64
Cold forging
of steels ... 3–36-42
Cold rolling
of Ni superalloys ... 1–12-13
Cold working
of Ni superalloys ... 4–24
of steel tubing ... 3–31
Commercial mill data processing computers ... 3–4-6
Composition
of strand cast steel slabs ... 4–51
Computers
in steel industry ... 3–1-4
commercial mill data processing ... 3–4-6
process control ... 3–6-7
use in simulation of heat transfer ... 3–9-13
Conduction
in heat transfer ... 3–9-12
Continuous casting
in development of Al alloy bearings ... 1–35-36
Continuous furnaces
six-tray furnaces ... 2–4
Convection
in heat transfer ... 3–12
Copper
brazing in vacuum furnaces ... 2–33-34
Copper alloys, specific types
Alloy 638
mechanical properties ... 1–64
oxide film ... 1–64
superplasticity ... 1–64
Copper brazing
in vacuum furnaces ... 2–29-30
Crawler tactor gearing
heat treatment ... 2–22-23
Creep
of Al alloys ... 1–26-28
of Ni superalloys ... 1–14
rate vs. deformation ... 4–59-61
Crevice corrosion
in ferritic stainless steels ... 2–46
Cutting
of steel tubing ... 3–31
DT test
in Al alloys ... 4–41-45
in fracture resistance ... 4–34
Diffusion bonding
of Ti composites ... 1–17-21
Drilling
of Al-B composites ... 3–19-20
Electric resistance welding
of steel tubing ... 3–30-31
Electroflux remelting
of Ni superalloys ... 4–25
Electrolytic cleaning salts ... 2–40
Emulsion cleaning
in aircraft industry ... 3–46
Exhaust valve seats
use of induction hardening ... 3–15
Fabrication
of Ni superalloys ... 4–23-25
of Ti composites ... 1–16-22
Fasteners
heat treating ... 2–20-21
Ferritic stainless steels
addition of Ti ... 2–45-47
engineering properties ... 2–41-47
pitting and crevice corrosion ... 2–46
pitting resistance ... 2–46
stabilization against sensitization ... 2–45-46
Ferritic stainless steels, specific types
11.5% Cr
properties ... 2–42-44
17% Cr
properties ... 2–44-45
Finishing
of steel tubing ... 3–31
Fitup
of Al alloy forgings ... 2–51
Forging
of automobile parts ... 2–35
of Fe superalloys ... 4–8-9
of Ni superalloys ... 1–13
Forming
of Al-B composites ... 3–21-25
Fracture
of Ti alloys ... 1–61-62
Fracture resistance
of Al alloys ... 4–39-49
C_V-NDT index ... 4–34-35
criteria ... 4–33-34
DT-K_{Ic} correlation ... 4–35
DT test ... 4–34
in Al alloys ... 4–37-38
in high-strength steels ... 4–36-37
in steels ... 4–35-36
measurement ... 4–34
mechanical aspects ... 4–31-33
microfracture aspects ... 4–33
NDT test ... 4–34
Fusion welding
of steel tubing ... 3–31
G phases
in Fe superalloys ... 4–5
γ precipitation
in Fe superalloys ... 4–2-3
Grain size
of Fe superalloys ... 4–27
Grinding
of Al-B composite ... 3–18
Hardening
in vacuum furnaces ... 2–29
Hardness
of Fe superalloys ... 4–27
Heat transfer
by conduction ... 3–9-12
by convection ... 3–12
by radiation ... 3–12
computer simulation ... 3–9-13
interface ... 3–9-13
Heat treatment ... 1–1-4
design ... 1–2
engineering requirements ... 1–3
equipment ... 1–3-4
materials ... 1–2-3
of automobile parts ... 2–35-37
of crawler tractor gearing ... 2–22-23
of fasteners ... 2–20-21
of Fe superalloys ... 4–9
of Ni superalloys ... 4–22-23
uniform quenching ... 1–4
High oxidation-potential cleaning salts ... 2–40
High-speed steels
use of salt baths ... 3–16-17
High-strength steels
fracture resistance ... 4–36-37
Homogenization
of Ni superalloys ... 1–11, 13
Hot rolling
of Ni superalloys ... 1–13
Hot working
of Ni superalloys ... 1–11-12; 4–23-24
Induction heating
of automobile parts ... 2–36
Induction hardening
in axle shafts ... 3–13
in bearing race clips ... 3–15
in bearing rib rings ... 3–15
in exhaust valve seats ... 3–15
in power train gears ... 3–14-15
in shaft buttons ... 3–14
in transmission shafts and spindles ... 3–14
Inert arc welding
of steel tubing ... 3–31
Information systems
Systems Test Management Information System ... 3–8-9
use in product test ... 3–8-9
Insulation
role of mixtures ... 3–34
stability ... 3–34
types of materials ... 3–33
use of zirconia ... 3–35
Internal soundness
of strand cast steel slabs ... 4–51-52
Iron
magnetic properties ... 1–46-47
Iron alloys, specific types
Fe-Co alloys
heat treatment ... 1–44-45
magnetic properties ... 1–44-45
Fe-Si alloys
magnetic properties ... 1–45
Iron superalloys
boron ... 4–7
carbides ... 4–5-7
casting ... 4–8
coated alloys ... 4–8
forging ... 4–8-9
G phase ... 4–5
γ' ... 4–5

γ′ precipitation in a FCC matrix ... 4–2
γ″ precipitation in a FCC matrix ... 4–3
grain boundary effects of carbides ... 4–6-7
heat treatment ... 4–9
Laves phase ... 4–5
matrix hardening of carbides ... 4–5-6
Mu phase ... 4–5
overaging ... 4–4
sigma phase ... 4–4-5
strengthening by intermetallic compounds ... 4–2-4
structure ... 4–2-7
trace elements ... 4–7
uncoated alloys ... 4–7-8
zirconium ... 4–7
Iron superalloys, specific types
Pyromet 860
effects of Ti and Al ... 4–25-30
γ′ and Eta solvus temperature ... 4–27-28
hardness and grain size ... 4–27
mechanical properties ... 4–28-29
microstructure ... 4–28
Laves phases
in Fe superalloys ... 4–5
Low oxidation-potential cleaning salts ... 2–40
Low-temperature baths ... 2–41
Machining
of Al alloy forgings ... 2–50
of Al-B composites ... 3–18-21
of Ni superalloys ... 4–24
Magnetic properties
of Fe ... 1–46-47
of Fe alloys ... 1–44-45
of Ni alloys ... 1–40-44
of stainless steels ... 1–45-46
Martempering
use of salt baths ... 3–16
Mechanical properties
in establishment of design stress values ... 1–22-30
of Al alloys ... 1–24-30
of Cu alloys ... 1–64
of Fe superalloys ... 4–28-29
of stainless steels ... 3–47-48
of strand cast steel slabs ... 4–52-55
Melting
of Ni superalloys ... 1–10-11, 13
Metallography
of Al alloys ... 1–36-37
Microcleanliness
of strand cast steel slabs ... 4–52
Microfracture
in fracture resistance ... 4–33
Microstructure
of Fe superalloys ... 4–28
Milling
of Al-B composites ... 3–18
Models
effect of failure rates ... 4–58
effect of scrap rates ... 4–57-58
in manufacture ... 4–56-57
Product Universal Modeling System ... 4–58
Molten salt baths
electrolytic cleaning salts ... 2–40
high oxidation-potential cleaning salts ... 2–40
low oxidation-potential cleaning salts ... 2–40
low temperature bath ... 2–41
maintenance ... 2–39
pollution control ... 2–41
uses ... 2–39-40
Mu phases
in Fe superalloys ... 4–5
NDT test
in fracture resistance ... 4–34
Neutral hardening
use of salt baths ... 3–16
Nickel alloys, specific types
Ni-Fe
heat treatment ... 1–40
magnetic properties ... 1–40
High permeability 49
magnetic properties ... 1–42-43
HyMu 80
magnetic properties ... 1–41-42
HyMu 800
heat treatment ... 1–40-41
magnetic properties ... 1–40-41
HyRa 49
magnetic properties ... 1–43-44
Nickel superalloys, specific types
Inconel 706
cold working ... 4–24
development ... 4–20-22
electroflux remelting ... 4–25
fabrication ... 4–23-25
heat treatment ... 4–22-23
hot working ... 4–23-24
machining ... 4–24
welding ... 4–24-25
U-700
annealing ... 1-12
bend ductility ... 1–15
casting ... 1–10-11, 13
cold rolling ... 1–13
creep ... 1–14
development ... 1–10-13
forging ... 1–13
homogenization studies ... 1–11, 13
hot rolling ... 1–13
hot working ... 1–11-12
loss of elements ... 1–12-13
melting ... 1–10-11, 13
production of solid bar from powder ... 1–48-50
properties ... 1–50
stress rupture properties ... 1–14
tensile properties ... 1–14
thermal stability ... 1–15
welding ... 1–15
Overaging
in Fe superalloys ... 4–4
Oxide films
in Al powder ... 3–28-29
in Cu alloys ... 1–64
Phase boundaries
of superalloys ... 4–17-18
Phase transformations
after straining ... 1–51-54
Pitting
in ferritic stainless steels ... 2–46
resistance in ferritic stainless steels ... 2–46
Plasticity
of stainless steels ... 3–47-48
Pollution control
use of molten salts ... 2–41
Power train gears
use of induction hardening ... 3–14-15
Process control computers ... 3–6-7
in steel industry ... 3–1-4
Product Universal Modeling System ... 4–58
Production
effect of failure rates ... 4–58
effect of scrap rate ... 4–57-58
Product Universal Modeling System ... 4–58
Quenching
agitation ... 2–17-19
design of tanks ... 2–19
dynamics ... 2–17
in heat treatment ... 1–4
time ... 2–18
R-curve
in Al alloys ... 4–42, 45-48
Radiation
in heat transfer ... 3–12
Recrystallization
after straining ... 1–55-56
Rupture strength
of Al alloys ... 1–26
Salt baths
advantages ... 3–17
applications ... 3–17
in austempering, martempering and annealing ... 3–16
in carburizing and neutral hardening ... 3–16
in heat treatment of high-speed steels ... 3–16
Shaft buttons
use of induction hardening ... 3–14
Sheetmetal vanes
vacuum heat treating ... 2–24
Shock hardening
of Al alloys ... 1–62-63
Shock pressure
effect on structure ... 1–56-57, 59-60
Shot peening
of Al alloy forgings ... 2–51
Sigma phases
in Fe superalloys ... 4–4-5
Sintering
of Al powder ... 3–26-30
Sizing
of steel tubing ... 3–31
Stainless steel tubing
uses ... 3–32
Stainless steels
magnetic properties ... 1–45-46
sintering in vacuum furnaces ... 2–32
Stainless steels, specific types
Type 304
isochronous stress-strain curves ... 1–31-33
mechanical properties ... 3–47-48
plasticity ... 3–47-48
strain rate ... 3–47-48
thermal recovery ... 3–47-48
Steel industry
use of process control computers ... 3–1-4
Steel plate
using strand cast steel slabs ... 4–50-55
Steel tubing
cold working ... 3–31
electric resistance welding ... 3–30-31
finishing ... 3–31
fusion inert arc welding ... 3–31
sizing and cutting ... 3–31
uses ... 3–32
Steels
fracture resistance ... 4–35-36
hardening in vacuum furnaces ... 2–32
use of synthetic quenchants ... 2–9-10
Steels, specific types
52100
cold forging ... 3–36-42
EX-2
cold forging ... 3–36-42
Straightening
of Al alloy forgings ... 2–50
Straining
effect on structure ... 1–51-60

Strain rates
of stainless steels ... 3–48
Strand cast steel slabs
composition ... 4–51
internal soundness ... 4–51-52
mechanical properties ... 4–52-55
microcleanliness ... 4–52
plate applications ... 4–50-55
surface quality ... 4–51
Strength
of Fe superalloys ... 4–2-4
Stress-corrosion cracking
of Al alloy forgings ... 2–47-52
Stress relieving
in vacuum furnaces ... 2–28-29; 2–33
Stress rupture properties
of Ni superalloys ... 1–14
Stress-strain
in stainless steels ... 1–31-33
Stress wave emission
in Ti alloys ... 1–61
Stretch forming
of Al-B composites ... 3–21-22
Structure
effect of strain rate ... 1–51-60
of Fe superalloys ... 4–2-7
of superalloys ... 4–13-17
phase transformation ... 1–51-54
recrystallization ... 1–55-56
shock pressure ... 1–56-57, 59-60
twinning ... 1–56, 59
Superalloys
phase boundaries ... 4–17-18
structure ... 4–13-17
superplasticity ... 4–18-19
thermomechanical treatment ... 4–18
Superplasticity
of Cu alloys ... 1–64
of superalloys ... 4–18-19
Surface quality
of strand cast steel slabs ... 4–51
Synthetic quenchants
disadvantages ... 2–10-11
use in Al ... 2–7-9
use in steel ... 2–9-10
use in Ti ... 2–10
System Test Management Information System ... 3–8-9
Tempering
in vacuum furnaces ... 2–33
of Al alloy forgings ... 2–49
Tensile properties
of Ni superalloys ... 1–14
of Ti alloy forgings ... 2–56-61
of Ti composites ... 1–20-21
Tensile strength
of Al alloys ... 1–25-26
Testing
of Al-B composites ... 3–18
Thermal recovery
of stainless steels ... 3–47-48
Thermal stability
of Ni superalloys ... 1–15
Thermomechanical treatment
of superalloys ... 4–18
Titanium
addition to ferritic stainless steels ... 2–45-47
addition to Fe superalloys ... 4–25-30
use of synthetic quenchants ... 2–10
Titanium alloy forgings, specific types
Ti-6Al-4V
powder ... 2–53-55
stepdown forgings ... 2–58-60
tensile properties ... 2–56-61
upset forgings ... 2–56-58
Titanium alloys, specific types
Ti-6Al-4V
fracture ... 1–61-62
stress wave emission ... 1–61
Titanium composites, specific types
Ti-6Al-4V-Al_2O_3
diffusion bonding ... 1–17-21
fabrication ... 1–16-22
reaction kinetics ... 1–17-20
tensile properties ... 1–20-21
Tool hardening
in vacuum furnaces ... 2–31
Tool steels
hardening in vacuum furnaces ... 2–33
Transmission shafts
use of induction hardening ... 3–14
Transmission spindles
use of induction hardening ... 3–14
Tufftride process ... 2–12-16
Twinning
after straining ... 1–56, 59
Vacuum furnaces
annealing ... 2–27-28; 2–33
annealing for stability ... 2–30
annealing to remove cold work effects ... 2–30-31
Cu brazing ... 2–33-34
hardening ... 2–29
hardening production steels ... 2–32
in heat treatment ... 2–27-31
in manufacture of business machines ... 2–27-31
sintering stainless steels ... 2–32
stress relieving ... 2–28-29
tempering and stress relieving ... 2–33
tool hardening ... 2–31
Vacuum heat treating
of blades ... 2–25
of cast vanes and blades ... 2–25
of sheetmetal vanes ... 2–24
problems ... 2–25-26
Welding
of Ni superalloys ... 1–15; 4–24-25
Yield strength
of Al alloys ... 1–26
Zirconia
as an insulating material ... 3–35
Zirconium
in Fe superalloys ... 4–7